

State of Utah DEPARTMENT OF NATURAL RESOURCES

DEPARTMENT OF NATURAL RESOURCES INSPECTION REDIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Michael O. Leavitt Governor Ted Stewart Executive Director James W. Carter Division Director

355 West North Temple 3 Triad Center, Suite 350 Salt Lake City, Utah 84180 Thispection	Partial: XX	Complete: 9-7&15-1995 / 8:3	_	
801-538-5340	Date & Time.	Date of Last Insp		
801-359-3940 (Fax) 801-538-5319 (TDD)		1		

= <u>-</u>					
Mine Name: Bear Canyon Mine County: Carbon Permit Number: ACT/015/025					
Permittee and/or Operator's Name: Co-Op Mining Company					
Business Address: P.O. Box 1245, Huntington, Utah 83428					
Type of Mining Activity: Underground XXX Surface Prep. Plant Other Other					
Company Official(s): Charles Reynolds					
State Officials(s): Peter Hess Federal Official(s):					
Weather Conditions: Warm Sunny					
Existing Acreage: Permitted-1531 Disturbed-24 Regraded- Seeded- Bonded-24					
Increased/Decreased: Permitted Disturbed Regraded Seeded Bonded					
Status:Exploration/_XX_Active/Inactive/Temporary Cessation/Bond Forfeiture					
Reclamation (Phase I/Phase II/Final Bond Release/LiabilityYear)					

REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
 - b. For partial inspections check only the elements evaluated.
- 2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

		EVALUATED	N/A	COMMENTS	NOV/ENF
1.	PERMITS, CHANGE, TRANSFER, RENEWAL, SALE				\Box
2.	SIGNS AND MARKERS	[XX]	\Box		\Box
3.	TOPSOIL		\Box	\Box	\Box
4.	HYDROLOGIC BALANCE:				
a.	DIVERSIONS	[XX]	\Box	[XX]	\Box
b.	SEDIMENT PONDS AND IMPOUNDMENTS	[XX]	\Box	[XX]	\Box
c.	OTHER SEDIMENT CONTROL MEASURES	[XX]	\Box	[XX]	
d.	. WATER MONITORING		\Box		ГŢ
e.	EFFLUENT LIMITATIONS			\Box	-[_]
5.	EXPLOSIVES		\Box		
6.	DISPOSAL OF EXCESS SPOIL/FILLS/BENCHES	\Box			لِـلِ
7.	COAL MINE WASTE/REFUSE PILES/IMPOUNDMENTS	\Box			<u>L</u>
	NONCOAL WASTE	[XX]			
9.	PROTECTION OF FISH, WILDLIFE AND				
	RELATED ENVIRONMENTAL VALUES		\Box		Щ
10.	SLIDES AND OTHER DAMAGE		\Box	Ц	ĻĻ
11.	CONTEMPORANEOUS RECLAMATION		Щ		ĻĻ
12.	BACKFILLING AND GRADING		\Box		ΙŢ
	REVEGETATION			Щ	لِــلِ
	SUBSIDENCE CONTROL		Ц	لِلِ	لِـلِ
15.	CESSATION OF OPERATIONS	\Box			
16.	ROADS:				
a.		[XX]	ĻĻ	[XX]	ĻĻ
b		Ц	بِـاِ	ĻĻ	上
17.			ĻĻ	닏	上
18.		Ļ	ĹŢ	<u> </u>	닏
	AVS CHECK (4th Quarter-April, May, June)(date	;) Ц	ĻĻ	닏	Щ
20.	AIR QUALITY PERMIT	ĻĻ	ĻĻ		ĻĻ
21	RONDING & INSURANCE	[]	11	1 1	11



INSPECTION REPORT

(Continuation sheet)

Page <u>2</u> of <u>3</u>

PERMIT NUMBER: ACT/015/025

DATE OF INSPECTION: 9-7&15-1995

(Comments are Numbered to Correspond with Topics Listed Above)

4a. HYDROLOGIC BALANCE: DIVERSIONS

With regard to NOV N94-46-4-1B, the Bear Canyon subsidence openings, the permittee has completed the work necessary to eliminate the hazards associated with the violation. This area was inspected on 9/7/95, at the request of the permittee to determine if the work was adequate at that point. It was determined that the opening on the western slope still needed additional material.

The drainage channel has been restored to the point that runoff should be conveyed down channel, rather than into the mine, as it previously did drain. Based on the 9/15/95 inspection, the violation is terminated. Monitoring of the repaired openings over the next few years will be necessary to determine whether additional work is necessary.

The permittee has submitted an amendment this date to this inspector to make changes in diversion ditch D-10D. Culvert C-2D, which routes drainage in the area west of the tipple was blocked completely by storm events which occurred on 8/22&23/95. Upon blockage, runoff continued, severely eroding the soil around the 15 inch flex pipe. The review of this amendment is currently pending.

4b. SEDIMENT PONDS AND IMPOUNDMENTS

The permittee is in the process of cleaning sediment pond "B", which is east of the new bath house facility. This is the pond which received all of the overflow from the Bear Canyon Creek when it overtopped its banks on 8/22&23/95. Much of the material which remains in the pond is still very wet. The continued rainy season in the area may prevent completion of this job this year. If that is the case, the permittee should determine if the volume of material which has been removed will allow recertification of the pond.

INSPECTION REPORT

(Continuation sheet)

Page <u>3</u> of <u>3</u>

PERM	IIT NUMBER: <u>ACT/015/025</u>	DATE OF INSPECTION: 9-7&15-1995			
	(Comments are Numbered to Corresp	ond with Topics Listed Above)			
4c.	OTHER SEDIMENT CONTROL MEASU	RES			
	The silt fences which were inspected on 9/be functioning normally.	11/95 were in good repair and appeared to			
Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.					
Copy of this Report:					
	Mailed to: Charles Reynolds (CO-OP) Given to: Joe Helfrich (DOGM) Date: September 19, 1998	Donna Griffin (OSM) Filed to: Price Field Office			
Inspec	ctor's Signature: Peter Hess	#46_			